

### Government of Western Australia Department of Environment Regulation

### **Annual Audit Compliance Report Form**

Environmental Protection Act 1986, Part V

Section A – Licence Details				
Licence number:	L4201/1991/11	Licence file number:	DEC6295	
Licence holder:	Water Corporation	Water Corporation		
Trading as:	Woodman Point Wastewater Treatment Plant			
ABN:	28 003 434 917			
Registered address:	629 Newcastle Street, LEEDERVILLE, WA 6007			
Reporting period:	01/07/2017 to 3	0 / 06 / 2018		

#### Section B – Statement of Compliance with Licence Conditions

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

 $\Box$ Yes – please complete:

- section C;
- section D if required; and
- sign the declaration in Section F.

#### $\boxtimes$ No – please complete:

- section C;
- section D if required;
- section E; and
- sign the declaration at Section F.

#### Section C – Statement of Actual Production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed Premises Category	Actual Production Quantity
54: Sewage facility	142,636 m <sup>3</sup> /d (details in Annual Environmental Report)
61: Liquid waste facility	9,722 tonnes (as above)

#### Section D - Statement of Actual Part 2 Waste Discharge Quantity

Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached.

Prescribed Premises Category	Actual Part 2 Waste Discharge Quantity

Section E – Deta	ils of Non-Compliance w	ith Licence Conditi	on		
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.					
Condition no:	1.3.5	Date(s) of non- compliance:	01/09/2017		
Details of non-com	pliance:				
H2S sensor reading	g >1,500ppb.				
What was the actua	al (or suspected) environmen	tal impact of the non-c	ompliance?		
NOTE – please attact compliance took plac	h maps or diagrams to provide i e.	nsight into the precise lo	cation of where the non-		
There was no envir					
H2S measuring inst sensor to register a	Cause (or suspected cause) of non-compliance: H2S measuring instrumentation faulted at the Tanker Receival Facility, which triggered the sensor to register a reading of 1,500ppb. The reason for such a setting is because the readings at and above 1500 ppb will generate an audible alarm which will trigger the maintenance team to				
	the H2S measuring device.				
On 01/09/2017, the chemical scrubber in the TRF was fully operational. The chemical pumps and the odour extractions fans were working. As such, there was no exceedance in H2S released to the environment.					
	gate any adverse effects of n	on-compliance and pre	event recurrence of the		
non-compliance: An electrician inspected the sensor and repaired the fault confirming that it was an instrument issue and not an increase in discharge. It was found that a moisture filter was clogged. The filter unit has been taken out and serviced. New filter shall be ordered for replacement.					
Was this non-compliance previously reported to DER?					
Yes, and					
Reported to I	DER verbally	Date: / /			
Reported to	DER in writing	Date: 04 / 09 /2017			

Section E – Deta	ils of Non-Compliance w	vith Licence Conditi	on
Please use a separ at a time during the	rate page for each condition vertige reporting period.	with which the licence	holder was non-compliant
Condition no:	1.3.5	Date(s) of non- compliance:	05/12/2017
Details of non-com	pliance:		
H2S sensor reading	g >1,500ppb.		
	al (or suspected) environmen h maps or diagrams to provide i e.		
	ed cause) of non-compliance:		
	lorite tanks went on low leve s there was hydrogen sulphic e dosing.		
Action taken to mitig non-compliance:	gate any adverse effects of n	on-compliance and pre	event recurrence of the
Received delivery of	chemical and chemical dosing c the discharge stack immediate		rmal and the H2S
Was this non-comp	liance previously reported to	DER?	
Yes, and			
Reported to I	DER verbally	Date: / /	
Reported to I	DER in writing	Date: 07 / 12 /2017	

Section E – Details of Non-Compliance with Licence Condition					
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.					
Condition no:	no: 1.3.5 Date(s) of non- compliance: 06/12/2017				
Details of non-com	Details of non-compliance:				
H2S sensor reading	g >1,500ppb.				
	al (or suspected) environmen h maps or diagrams to provide i e.				
There was no envir	,				
Cause (or suspecte	d cause) of non-compliance:				
Reinstated and con	e leak identified and hypochl nmenced dosing at 2:22pm. I ugh the stack of hydrogen su	During repair and fixing			
	gate any adverse effects of r	on-compliance and pre	event recurrence of the		
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance: Once the leak was repaired chemical dosing operations returned to normal and the H2S concentrations exiting the discharge stack immediately dropped to near zero. The performance of the chemical scrubbers was monitored until the operators were satisfied that normal operations had been restored.					
Was this non-compliance previously reported to DER?					
🛛 Yes, and			1000000		
Reported to I	DER verbally	Date: / /			
Reported to [	DER in writing	Date: 07 / 12 /2017			

	ans of Non-Compliance w	vith Licence Condi	uon
Please use a sepa at a time during the	rate page for each condition eroporting period.	with which the licence	e holder was non-compliant
Condition no:	1.3.5	Date(s) of non- compliance:	07/12/2017
Details of non-com	pliance:		
H2S sensor readin	g >1,500ppb.		
	al (or suspected) environmer th maps or diagrams to provide te.		
There was no envir	and the second sec		
There was an elect operating. When the	ed cause) of non-compliance: rical fault at the WWTP which re aeration at the SBR was re SBR bioselectors which resu	h resulted in the aerat	s a large amount of foul air
There was an elect operating. When the extracted from the Action taken to miti non-compliance: Operations continued concentrations. Leve	rical fault at the WWTP which e aeration at the SBR was re	h resulted in the aerat instatement there was lted in a surge of H2S non-compliance and p I sodium hypochlorite w inutes. The performance	s a large amount of foul air in the chemical scrubbers. revent recurrence of the as dosed to reduce the H2S e of the chemical scrubbers
There was an elect operating. When the extracted from the Action taken to miti non-compliance: Operations continued concentrations. Leve was monitored until t	rical fault at the WWTP which e aeration at the SBR was re SBR bioselectors which resu gate any adverse effects of r to run as normal and additiona Is returned to normal after 18 m	h resulted in the aerat instatement there was lted in a surge of H2S non-compliance and p I sodium hypochlorite w inutes. The performance normal operations had	s a large amount of foul air in the chemical scrubbers. revent recurrence of the as dosed to reduce the H2S e of the chemical scrubbers
There was an elect operating. When the extracted from the Action taken to miti non-compliance: Operations continued concentrations. Leve was monitored until t	rical fault at the WWTP which e aeration at the SBR was re SBR bioselectors which resu gate any adverse effects of r to run as normal and additiona Is returned to normal after 18 m he operators were satisfied that	h resulted in the aerat instatement there was lted in a surge of H2S non-compliance and p I sodium hypochlorite w inutes. The performance normal operations had	s a large amount of foul air in the chemical scrubbers. revent recurrence of the as dosed to reduce the H2S e of the chemical scrubbers
There was an elect operating. When the extracted from the Action taken to miti non-compliance: Operations continued concentrations. Leve was monitored until t Was this non-comp	rical fault at the WWTP which e aeration at the SBR was re SBR bioselectors which resu gate any adverse effects of r to run as normal and additiona Is returned to normal after 18 m he operators were satisfied that	h resulted in the aerat instatement there was lted in a surge of H2S non-compliance and p I sodium hypochlorite w inutes. The performance normal operations had	s a large amount of foul air in the chemical scrubbers. revent recurrence of the as dosed to reduce the H2S e of the chemical scrubbers

Section E – Deta	ils of Non-Compliance w	ith Licence Condition	on			
Please use a separate a time during the	rate page for each condition vertice reporting period.	with which the licence h	nolder was non-compliant			
Condition no:	Condition no:1.3.5Date(s) of non- compliance:02/02/2018					
Details of non-com	Details of non-compliance:					
H2S sensor reading	g >1,500ppb.					
	al (or suspected) environmen h maps or diagrams to provide i		Contraction of the local division of the loc			
There was no envir						
	ed cause) of non-compliance: ipework leak on the Train 2 s		ubber.			
Action taken to miti non-compliance:	gate any adverse effects of n	on-compliance and pre	event recurrence of the			
The pipework was re	paired and once dosing recomm hemical scrubber was monitored restored.					
Was this non-comp	liance previously reported to	DER?				
Yes, and						
Reported to	DER verbally	Date: / /				
Reported to DER in writing Date: 03 / 02 /2018						

	ails of Non-Compliance w	ith Licence Conditi	on
Please use a sepa at a time during the	rate page for each condition error to reporting period.	with which the licence I	nolder was non-compliant
Condition no:	1.3.5	Date(s) of non- compliance:	04/02/2018
Details of non-com	pliance:		
H2S sensor readin	g >1,500ppb.		
	al (or suspected) environments th maps or diagrams to provide i te.		
There was no envir			
	ed cause) of non-compliance: ault at the sodium hypochlorit		ed them from starting
			a thom nom starting.
	gate any adverse effects of n	on-compliance and pre	
non-compliance: The duty pump was t	gate any adverse effects of n urned on and the H2S level retu red until the operators were sati	rned to normal. The perfo	event recurrence of the
non-compliance: The duty pump was t scrubber was monitor	urned on and the H2S level retu	rned to normal. The perfo sfied that normal operatio	event recurrence of the
non-compliance: The duty pump was t scrubber was monitor Was this non-comp	urned on and the H2S level retu red until the operators were sati	rned to normal. The perfo sfied that normal operatio	event recurrence of the
non-compliance: The duty pump was t scrubber was monitor	urned on and the H2S level retu red until the operators were satis	rned to normal. The perfo sfied that normal operatio	event recurrence of the

Section E – Details of Non-Compliance with Licence Condition						
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.						
Condition no:	Condition no:1.3.5Date(s) of non- compliance:05/02/2018					
Details of non-com	oliance:					
H2S sensor reading	g >1,500ppb.					
	al (or suspected) environmen h maps or diagrams to provide i e.					
i nere was no envir	There was no environmental impact.					
Cause (or suspecte	ed cause) of non-compliance:					
The cause was a fa	ult at the sodium hypochlorit	e pump which prevent	them from starting.			
non-compliance:	gate any adverse effects of n					
	urned on and the H2S level retu ed until the operators were sati					
Was this non-comp	liance previously reported to	DER?				
⊠ Yes, and						
Reported to	DER verbally	Date: / /				
Reported to DER in writing Date: 07 / 02 /2018						

Section E – Deta	ails of Non-Compliance w	ith Licence Condi	tion
Please use a sepa at a time during the	rate page for each condition e reporting period.	with which the licence	e holder was non-compliant
Condition no:	1.3.5	Date(s) of non- compliance:	07/03/2018
Details of non-com	pliance:		
H2S sensor readir	ng >1,500ppb.		
	al (or suspected) environmen ch maps or diagrams to provide i ce.		
There was no envi			
	ed cause) of non-compliance: potable water shutdown at the of time.		he chemical scrubbers lost
The cause was a p water for a period Action taken to mit	ootable water shutdown at the	plant, which meant t	
The cause was a p water for a period Action taken to mit non-compliance: The water supply wa	ootable water shutdown at the of time. igate any adverse effects of r as returned to the chemical scrub chemical scrubber was monitored	plant, which meant t non-compliance and p obers and the H2S level	prevent recurrence of the
The cause was a p water for a period Action taken to mit non-compliance: The water supply wa performance of the c operations had been	ootable water shutdown at the of time. igate any adverse effects of r as returned to the chemical scrub chemical scrubber was monitored	plant, which meant t non-compliance and p obers and the H2S level d until the operators we	prevent recurrence of the
The cause was a p water for a period Action taken to mit non-compliance: The water supply wa performance of the c operations had been	ootable water shutdown at the of time. igate any adverse effects of r as returned to the chemical scrub chemical scrubber was monitored restored.	plant, which meant t non-compliance and p obers and the H2S level d until the operators we	prevent recurrence of the
The cause was a p water for a period Action taken to mit non-compliance: The water supply wa performance of the c operations had been Was this non-comp	ootable water shutdown at the of time. igate any adverse effects of r as returned to the chemical scrub chemical scrubber was monitored restored.	plant, which meant t non-compliance and p obers and the H2S level d until the operators we	prevent recurrence of the

Section E – Details of Non-Compliance with Licence Condition					
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.					
Condition no:	ondition no: 1.3.5 Date(s) of non- compliance: 14/03/2018				
Details of non-com	Details of non-compliance:				
H2S sensor reading	g >1,500ppb.				
	al (or suspected) environment in maps or diagrams to provide it e.				
	There was no environmental impact.				
Cause (or suspecte	d cause) of non-compliance	:			
cleaning was requir	citric acid cleaning of the tw ed due to a build-up of mate pumps (caustic and hypoch	rial on the tellerites and	to complete the works		
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance: Cleaning of the secondary scrubber is part of standard operational maintenance and once completed, all pumps and valves were de-isolated so dosing could recommence and normal operation resume. The H2S levels then returned to normal. The performance of the chemical scrubber was monitored until the operators were satisfied that normal operations had been restored.					
Was this non-comp	liance previously reported to	DER?			
Yes, and					
Reported to I	Reported to DER verbally Date: / /				
Reported to DER in writing Date: 07 / 02 /2018					

#### **Section F – Declaration**

IWe declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular<sup>1</sup>. I/We consent to the Annual Audit Compliance Report being published on the Department of Environment Regulation's (DER) website.

Signature <sup>2</sup> :		Signature:
Name: (printed)	Mark Leathersich	Name: (printed)
Position:	General Manager Operations	Position:
Date:	718117	Date:
Seal (if signing under seal):		

<sup>&</sup>lt;sup>1</sup> It is an offence under section 112 of the Environmental Protection Act 1986 for a person to give information on this form that to their knowledge is false or misleading in a material particular.  $^{2}$  AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the

licence holder.

---

•

•

.

. . .

.

.

ł