

Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V

Section A – Licence Details			
Licence number:	L7969/2004/3	Licence file number:	DER2013/000991
Licence holder:	Northern Star Resources Ltd		
Trading as:	Northern Star Resources Ltd		
ACN:	092 832 892		
Registered address:	Level 1, 388 Hay Street, Subiaco WA 6008		
Reporting period:	01/07/2020 to 30/06/2021		

Section B – Statement of Compliance with Licence Conditions

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

 \Box Yes – please complete:

- section C;
- section D if required; and
- sign the declaration in Section F.

 \boxtimes No – please complete:

- section C;
- section D if required;
- section E; and
- sign the declaration at Section F.

Section C – Statement of Actual Production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed Premises Category	Actual Production Quantity	
Category 5: Processing or beneficiation of metallic or non-metallic ore	0 tonnes	
Category 52: Electric power generation	0.28MW	
Category 63: Inert landfill site	0.71 tonnes	
Category 64: Landfill facility	0.71 tonnes	
Category 85: Sewage facility	224kL total	

Section D – Statement of Actual Part 2 Waste Discharge Quantity			
Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached.			
Prescribed Premises Category Actual Part 2 Waste Discharge Quantity			
5	0 tonnes		

Section E – Deta	Section E – Details of Non-Compliance with Licence Condition			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.				
Condition no:	9	Date(s) of non- compliance:	October 2020 and April 2021	
Details of non-comp	pliance:			
-	collected and tested from the 4/3. Samples were taken in S	-		
What was the actua	al (or suspected) environmen	tal impact of the non-c	ompliance?	
NOTE – please attac compliance took plac	h maps or diagrams to provide i e.	nsight into the precise lo	cation of where the non-	
Location of sewage	treatment plant shown in att	ached Map 1.		
Suspected environmental impact is negligible, samples were missed due to staff availability. The sewage treatment plant is catering to 6 persons and has a capacity of 150 persons. Physical parameters have remained stable from this sample point.				
Cause (or suspecte	ed cause) of non-compliance:			
Staffing availability and human error.				
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:				
Additional training provided to new staff members to ensure sewage sampling is completed at the appropriate time.				
Was this non-compliance previously reported to DWER?				
Yes, and				
Reported to	DWER verbally	Date: / /		
Reported to	DWER in writing	Date: / /		

Section E – Details of Non-Compliance with Licence Condition					
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.					
Condition no:	5(a) Date(s) of non- compliance: October 2020 and April 2021				
Details of non-comp	liance:				
-	PMB05 not sampled in line with the DWER Licence L7969/2004/3 due to bore being dry during the October 2020 and April 2021 sampling run.				
What was the actua	l (or suspected) environmen	tal impact of the non-c	ompliance?		
NOTE – please attach compliance took place	n maps or diagrams to provide i e.	nsight into the precise lo	cation of where the non-		
samples are taken at nearby bores					
Cause (or suspected	d cause) of non-compliance:				
Action taken to mitig non-compliance:	gate any adverse effects of n	on-compliance and pro	event recurrence of the		
Samples will be taken when bore is no longer dry and samples are taken at nearby bores.					
Was this non-compliance previously reported to DWER?					
Yes, and					
Reported to D	OWER verbally	Date: / /			
Reported to D	OWER in writing	Date:			

Section E – Details of Non-Compliance with Licence Condition				
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.				
Condition no:	5(a)	Date(s) of non- compliance:	January	
Details of non-comp	bliance:			
	amples were not collected an 969/2004/3 during the Januar			
What was the actua	al (or suspected) environmen	tal impact of the non-c	ompliance?	
NOTE – please attact compliance took plac	h maps or diagrams to provide i e.	nsight into the precise lo	cation of where the non-	
	nental impact is negligible, sans with no concerning results		for testing in April 2021 as	
Cause (or suspecte	ed cause) of non-compliance:			
Flight disruptions restricted sample transport to Perth laboratory. Alternative freight arrangements via truck were not suitable due to holding time restrictions.				
Action taken to mitig	gate any adverse effects of n	on-compliance and pro	event recurrence of the	
Samples were collected in April 2021 following the recommencement of flights.				
Was this non-compliance previously reported to DWER?				
Yes, and				
Reported to I	DWER verbally	Date: / /		
Reported to I	to DWER in writing Date:			

Section E – Details of Non-Compliance with Licence Condition				
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.				
Condition no:	4	Date(s) of non- compliance:	August 2020	
Details of non-comp	bliance:			
deposited on the TS	ed the tailings storage facility SF embankments, perimeter Io tailings were deposited be	access road, adjacent	vegetation and adjacent	
What was the actua	al (or suspected) environmen	tal impact of the non-c	ompliance?	
NOTE – please attact compliance took plac	h maps or diagrams to provide i e.	nsight into the precise lo	cation of where the non-	
Suspected environmental impact is low. Where possible, the tailings was collected and deposited back into the TSF. Work was completed to ensure tailings on the embankments were captured at the base of the TSF once rain had fallen. It was then transferred back into the TSF.				
Cause (or suspecte	d cause) of non-compliance:			
High winds creating extreme dust conditions, out of the ordinary for this site.				
Action taken to mitig	gate any adverse effects of n	on-compliance and pre	event recurrence of the	
Application of Gluon (polymer) to TSF to bind the tailings particles together and minimise dust generation during any future wind events.				
Was this non-compliance previously reported to DWER?				
Yes, and				
Reported to I	DWER verbally	Date: / /		
Reported to I	DWER in writing	Date: 04 / 11 / 2020		

Section F – Declaration

I/We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular ¹ . I/We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.				
Signature ² :			Signature:	
Name: (printed)			Name: (printed)	
Position:			Position:	
Date:			Date:	
Seal (if signing under seal):				

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.