Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V

Section A – Licence Details			
Licence number:	L8579/2011/2	Licence file number:	2012/006902-1
Licence holder:	AngloGold Ashanti Australia Limited		
Trading as:	AngloGold Ashanti Australia Limited		
ACN:	008 737 424		
Registered address:	Level 10, 140 St Georges Tce, Perth WA 6000		
Reporting period:	01/01/2023 to 31/12/2023		

Section B – Statement of Compliance with Licence Conditions

Did you comply with all of your licence conditions during the reporting period? (Please tick the appropriate box)

☐Yes – please complete:

- · section C;
- section D if required; and
- sign the declaration in Section F.

⊠No – please complete:

- · section C;
- section D if required;
- section E; and
- · sign the declaration at Section F.

Section C - Statement of Actual Production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed Premises Category	Actual Production Quantity
05 - Processing or beneficiation of metallic or non-metallic ore	3,902,635 tonnes
06 - Mine dewatering	790,861.9 tonnes
52 - Electric power generation	48 MW
54 - Sewage facility	194.96 m³ per day
57 - Used tyre storage	<1,000
64 - Class II putrescible landfill site	2,889.32 tonnes

Section D – Statement of Actual Part 2 Waste Discharge Quantity

documentation is to be attached.	intity for this reporting period. Supporting
Prescribed Premises Category	Actual Part 2 Waste Discharge Quantity
Tailings	3,902,635 tonnes
Mine Dewatering	790,861.9 tonnes
Continue Details of New Commission	vide License Condidien
Section E – Details of Non-Compliance v	ndition with which the licence holder was
non-compliant at a time during the repo	
Condition no:	Date(s) of non- compliance: 2023
Details of non-compliance:	
Covering of the landfill was not undertaken fort	nightly.
What was the actual (or suspected) environme	ntal impact of the non-compliance?
NOTE – please attach maps or diagrams to provide compliance took place.	insight into the precise location of where the non-
Minimal impact to the receiving environment du Rock Landform and it is well within the Premise Cover material has been placed routinely, just i	
Cause (or suspected cause) of non-compliance):
Staff turnover and lack of clarity for accountabil	ity for the activity.
Action taken to mitigate any adverse effects of compliance:	non-compliance and prevent recurrence of the non-
AGAA is currently investigating: new accountabilities for the landfill, and new system to ensure the landfill is bad In addition, a new landfill will soon be replacing	kfilled in a timely manner.
Was this non-compliance previously reported to	DWER?
No	
Reported to DWER verbally	Date: / /
Reported to DWER in writing	Date:
DWER reference number for this report is ICMS 61245	

Condition no:	4	Date(s) of non-complian	ce:	2023
Details of non-compliance:				
Windblown rubb	ish collect	on did not occur weekly		
What was the a	ctual (or su	spected) environmental	impact of the non-compli	ance?
NOTE – please a compliance took p		or diagrams to provide insi	ght into the precise location	of where the non-
Waste Rock Lar Iandfill).	ndform and	l it is well within the Pren	o the location of the landfi nises boundary (Figure 1 ot always on a weekly ba	Location of the
		e) of non-compliance:	or always on a weekly ba	313.
Staff turnover a	nd lack of o	clarity for accountability f	or the activity.	
Action taken to non-compliance	_	y adverse effects of non	-compliance and prevent	recurrence of the
AGAA is current new acc new sys	tly investig countabilitie stem to ens	es for the landfill, and	ucted in a timely manner. s one.	
Was this non-co	mpliance p	previously reported to D\	WER?	
No				
Reported to	DWER ver	bally	Date: / /	
Reported to	DWER in v	vriting	Date:	
DWER referer 61245	ice number	for this report is ICMS		



Figure 1 Landfill Location

Condition no:		Date(s) of non- compliance:	December 2023
Details of non-comp	Details of non-compliance:		
No dewatering discharge sample was collected in Q4 2023 as there was no water being discharged on the days in December when the technician went to collect the samples.			
What was the actua	l (or suspected) environmen	ntal impact of the non-	-compliance?
NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.			
Technical non-compliance only, no impact to the receiving environment. Please see Figure 2 for the location of Dewatering Discharge Point			
Cause (or suspecte	Cause (or suspected cause) of non-compliance:		
Monitoring schedule did not allow sufficient time to go back for a sample if discharge was not occurring at the time of planned sampling.			
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:			
The monitoring scheduled will be amended to the first month of the quarter, in order to provide more opportunity for sampling days if they are required. However, this will be staged to maintain compliance with the timing specified in Condition 15.			
Was this non-compliance previously reported to DWER?			
No			
Reported to DW	ER verbally	Date: / /	
Reported to DW	ER in writing	Date:	
DWER reference r 61245	number for this report is ICMS		




Figure 2 Dewatering Discharge Point Location

Section F – Declaration			
I/We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular ¹ . I/We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.			
Signature:		Signature:	
Name: (printed)		Name: (printed)	
Position:		Position:	
Date:	27/02/24	Date:	
Seal (if signing under seal):			

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.