



Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V

Section A – Licence Details			
Licence number:	L8891/2015/1	Licence file number:	DER2015/000562
Licence holder:	Central Iron Ore Limited		
Trading as:	British King Gold Mine		
ACN:	072871133		
Registered address:	Suite 1, Level 2 49-51 York Street SYDNEY NSW 2000		
Reporting period:	1 / 7 / 2024 to 30 / 6 / 2025		

Section B – Statement of Compliance with Licence Conditions
Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)
☐ Yes – please complete: • section C; • section D if required; and • sign the declaration in Section F.
☒ No – please complete: • section C; • section D if required; • section E; and • sign the declaration at Section F.


Section C – Statement of Actual Production	
Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.	
Prescribed Premises Category	Actual Production Quantity
Cat 7 – Vat or insitu leaching of metal	Nil Production since 2017

Section D – Statement of Actual Part 2 Waste Discharge Quantity	
Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached.	
Prescribed Premises Category	Actual Part 2 Waste Discharge Quantity
Cat 7 – Vat or insitu leaching of metal	Nil Production since 2017

Section E – Details of Non-Compliance with Licence Condition			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.			
Condition no:	3.4.1	Date(s) of non-compliance:	Date of Construction
Details of non-compliance:			
The Groundwater Monitoring Bores around the Vat Leach were not monitored as per Table 3.4.1			
What was the actual (or suspected) environmental impact of the non-compliance?			
NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.			
The British King Gold Mine remains on care and maintenance, with no prescribed activities taking place since 2017. The construction of the Vat Leach cells was not completed and the Vat Leach facility underwent limited commissioning and production ceased. No further leaching has taken place. Therefore, the environmental impact of this non-compliance is considered low.			
Cause (or suspected cause) of non-compliance:			
The Vat Leach Facility was never fully commissioned and the Groundwater Monitoring program was not implemented.			
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:			
Central Iron Ore believe that since the Vat Leach was not fully commissioned no emissions to groundwater has occurred and therefore no groundwater monitoring is required. There is no evidence that Environmental Values have been impacted. This was reported in the 2021, 2022 and 2023 AACR.			
Was this non-compliance previously reported to DWER? Yes			
☐ Yes, and			
☐ Reported to DWER verbally		Date: / /	
☒ Reported to DWER in writing		Date: 24 / 02 / 2022	

Section F – Declaration

I/We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular¹. I/We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

Signature ² :		Signature:	
Name: (printed)		Name: (printed)	
Position:		Position:	
Date:		20 July 2025	Date:
Seal (if signing under seal):			

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.