



Licence Number L8650/2012/1

Licence Holder Chevron Australia Pty Ltd

ACN 086 197 757

File Number: DER2014/002939

Premises Ashburton North Village and LNG Plant Temporary Utilities

Part of Lots 1577 on Plan 72843, 560 on Plan 71346, 509 on Plan 69198, 519 on Plan 69198, 561 on Plan 71346, 564 on Plan 71346, 565 on Plan 71346, 575 on Plan 71345, 570 on Plan 71345, 567 on Plan 71345, 569 on Plan 71345 and 400 on Plan 72906

TALANDJI WA 6710

Date of Amendment 6 May 2019

Amendment

The Chief Executive Officer (CEO) of the Department of Water and Environmental Regulation (DWER) has amended the above Licence in accordance with section 59 of the *Environmental Protection Act 1986* (EP Act), as set out in this Amendment Notice. This Amendment Notice constitutes written notice of the amendment in accordance with section 59B(9) of the EP Act.

Manager, Process Industries

an officer delegated under section 20 of the *Environmental Protection Act 1986* (WA).

Definitions and interpretation

Definitions

In this Amendment Notice, the terms in Table 1 have the meanings defined.

Table 1: Definitions

Term	Definition
Delegated Officer	an officer under section 20 of the EP Act
Department	means the department established under section 35 of the <i>Public Sector Management Act 1994</i> and designated as responsible for the administration of Part V, Division 3 of the EP Act.
EP Act	<i>Environmental Protection Act 1986</i> (WA)

Amendment Notice

This amendment is made pursuant to section 59 of the *Environmental Protection Act 1986* (EP Act) to amend the Licence issued under the EP Act for a prescribed premises as set out below. This notice of amendment is given under section 59B(9) of the EP Act.

Amendment description

Chevron Australia Pty Ltd (the Licence Holder) operate the Ashburton North Village and LNG temporary facilities under Licence L8650/2012/1.

This notice is limited to an administrative amendment under section 59(1)(e)(i) of the EP Act to correct a clerical error in Condition 2.3.2. The Licence Holder notified the Department of the clerical error and Delegated Officer has elected to initiate an amendment to make the correction.

Amendment history

Table 2 provides the amendment history for L8650/2012/1.

Table 2: Licence amendments

Instrument	Issued	Amendment
L8650/2012/1	28/06/2012	New application – category 85 (Pioneer Camp)
	20/12/2012	Amendment to add the Fly Camp and 456-bed camp expansion.
	21/11/2013	Amendment to add the 600 EP STP and second irrigation field.
	27/11/2014	Amendment to add Trains 1 to 3 of the Construction Village STP, remove the Pioneer Camp STP, Fly Camp STP and 456 Bed Camp Expansion STP, and upgrade the design capacity of the 600 EP STP. Addition of the first three stages of the Construction Village Power Station. Addition of the LNG Plant Long Term Fuel Facility.
	20/08/2015	Amendment to allow the Fly Camp STP to be recommissioned and allow the reuse of treated effluent for irrigating the sports oval.
	29/04/2016	Amendment by notice to extend the date of expiry to 1 July 2021.
	30/06/2017	Amendment Notice 1. Addition of Stage 4 of the Construction Village Power Station, Construction Village Expansion Camp STP, and Train 4 of the Construction Village STP.
	18/09/2018	Transfer from Bechtel (Western Australia) Pty Ltd to Chevron Australia Pty Ltd.
	13/12/2018	Amendment Notice 2. Addition of Temporary Marine Outfall. Remove Category 52: Electric power generation, the Fly Camp STP and conditions relating to reuse of wastewater for dust suppression.
	6/5/2019	Amendment Notice 3. Administrative amendment to correct a clerical error in Condition 2.3.2.

Decision

The Delegated Officer has granted the amendment notice to correct a clerical error in Condition 2.3.2 as described below.

Amendment

1. Condition 2.3.2 of the Licence is amended by the deletion of the text shown in strikethrough below and the insertion of the red text shown in underline below:
 - 2.3.2 *The Licensee must ensure that if monitoring of any parameter undertaken in accordance with Condition ~~3.3.1~~ 3.3.2 indicates an exceedance of the Environmental Quality Guideline specified in Table 2.3.1, an investigation will be undertaken to determine if there has been an exceedance of the relevant Environmental Quality Standard.*