



CEO-initiated amendment to licence

Division 3, Part V *Environmental Protection Act 1986*

Licence number	L7413/1998/10
Licence holder	Cretta Pty Ltd
Application number	APP-0035287
Premises	Howard Park Wines 137 Fifty-One Road COWARAMUP 6284
Date of report	20/05/2026
Status of report	Revised licence granted

1. Scope of amendment

1.1 Amendment summary

Howard Park Wines Pty Ltd (licence holder) hold licence L7413/1998/10, issued under Part V Division 3 of the *Environmental Protection Act 1986*.

In 2025 the department conducted a review of the licence as part of issuing a replacement. On 31 October 2025, the licence holder contacted the Department of Water and Environmental Regulation (the department) requesting a series of administrative type to the licence to reflect current operations of the wastewater treatment plant, wastewater storage, irrigation and monitoring requirements.

2. Decision

The delegated officer has determined to initiate the amendment as an administrative change to correct unintended errors and take the opportunity to make administrative updates such as removing obligation conditions that have been satisfied and amending irrigated wastewater limit values. A summary of the amendments can be seen in the table below.

3. Consultation

The draft licence was provided to the licence holder for comment on 6 May 2026. On 15 May 2025, the licence holder provided a response to the following conditions (department response in **bold**):

- Condition 1, Table 1, Item 5(d): amend to allow the spreading of stabilised marc up to the premises boundary if the neighbouring property is owned or operated by the licence holder. **Condition amended.**
- Condition 6, Table 4: amend to include a limit for the May irrigation period. **Condition amended.**

3.1 Summary of changes

The below table provides a summary of the updates and will act as a record of implemented changes to the licence.

Condition / table	Description
Condition 1, Table 1. Item 3, Column 3 (a).	<i>Removal of mention high-level alarms and high-level markers as they do not exist on the premises.</i>
Condition 1, Table 1. Item 3, Column 3 (c).	<i>Deleted condition as management of overtopping covered in separate condition.</i>
Condition 1, Table 1. Item 4, Column 3 (b).	<i>Updated to allow wastewater irrigation to occur up to the 15 of May due to the risk of soils hydraulic capacity being exceeded is low during this time and separate conditions prevent irrigation occurring during or after a high rainfall event.</i>
Condition 1, Table 1, Item 5, Column 3 (d).	<i>Allow for the spreading of stabilised marc up to the premises boundary</i>
Condition 1, Table 1. Item 6, Column 3 (g).	<i>Updated for the application of gypsum following soil ESP monitoring results (>6%) to prevent excessive application of gypsum to the land application area where soil quality is optimal.</i>
Condition 2 – 4 and Schedule 3: Figure 4.	<i>Deleted conditions as the works for monitoring wells has been completed and construction report submitted.</i>
Condition 2, Table 2.	<i>Updated limit values for parameters “SAR:EC” and “Electrical conductivity” to reflect the soil quality data and salinity tolerance of cropping species.</i>

<i>Condition 6, Table 4.</i>	<i>Updated to allow a May 1st to 15th hydraulic loading limit of 500 kL of treated wastewater application to reflect the allowance of treated wastewater application during the beginning of May.</i>
<i>Condition 7</i>	<i>Deleted condition as coppicing plan has been submitted.</i>
<i>Condition 4, Table 5.</i>	<i>Existing table footnote 2 added to "Potassium" to correct missed inclusion from the licence review.</i>
<i>Condition 12</i>	<i>Removal of breach of specified limit from condition as the licence holder risks non-compliance due to lab results turn around.</i>