Annual Audit Compliance Report Form Environmental Protection Act 1986, Part V

Section A – Licence Details				
Licence number:	L6326/1991/3	Licence file number:	2010/005966	
Licence holder:	Water Corporation			
Trading as:	Lancelin Wastewater Treatment Plant			
ABN:	28 003 434 917			
Registered address:	629 Newcastle Street, LEEDERVILLE, WA 6007			
Reporting period:	01 / 01 / 2023 to 30 / 06 / 2024			

Section B - Statement of Compliance with Licence Conditions

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

☐Yes – please complete:

- · section C;
- · section D if required; and
- · sign the declaration in Section F.

⊠No – please complete:

- · section C;
- section D if required;
- section E; and
- sign the declaration at Section F.

Section C - Statement of Actual Production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed Premises Category	Actual Production Quantity	
54	98 m³/day (includes K130 waste)	
61	1.04 m ³ /day (K210, K110 and L150 waste type)	

Section D – Statement of Actual Part 2 Waste Discharge Quantity Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached. Prescribed Premises Category Actual Part 2 Waste Discharge Quantity

Section E – Details of Non-Compliance with Licence Condition						
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.						
Condition no:	W3 (ii)	Date(s) of non- compliance:	03/06/2024			
Details of non-comp	oliance:					
Condition W3 (ii) states that the licensee shall manage and operate the wastewater treatment ponds in a manner such that: (ii) overtopping of the ponds shall not occur except as a result of extreme rainfall events. During several events over the month of June 2024 an estimated 10-24kL of wastewater overflowed from the infiltration pond at the WWTP to the environment via an outlet pipe.						
What was the actua	al (or suspected) environmen	tal impact of the non-c	ompliance?			
NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.						
No environmental impact has been detected currently.						
Cause (or suspecte	ed cause) of non-compliance:					
High rainfall in the region and reduced capacity at the WWTP across both ponds.						
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:						
Health and safety signage was erected, and overflow was reported to DWER. Tankering was then undertaken from Lancelin WWTP to Jurien Bay WWTP to reduce flows into plant. This issue is set to be rectified once Infiltration Pond 2 is construction as part of Works Approval W6716/2022/1.						
Was this non-compliance previously reported to DER?						
⊠ Yes, and □ No						
Reported to	DER verbally	Date:				
⊠ Reported to	DER in writing	Date: 05/06/2024				

Section F - Declaration

I/We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular ¹ . I/We consent to the Annual Audit Compliance Report being published on the Department of Environment Regulation's (DER) website.					
Signature ² :		Signature:			
Name: (printed)		Name: (printed)			
Position:		Position:			
Date:	24/09/2024	Date:			
Seal (if signing under seal):					

 $^{^{1}}$ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.