Annual Audit Compliance Report form

Environmental Protection Act 1986, Part V

Section A – Licence Details				
Licence Number:	L6820/1993/12	Licence File Number: DER2014/000766-1		
Licence Holder:	Robe River Mining Co Pty Ltd			
Trading as:	Robe River Iron Associates			
ACN:	008 694 246			
Registered address:	Level 18, Central Park. 152-158 St. Georges Terrace, PERTH WA 6000			
Reporting period:	1 January 2023 to 31 December 2023			

Section B – Statement of compliance with licence conditions			
Did you	Did you comply with all of your licence conditions during the reporting period?		
Yes	Please complete Sections C, D (if required) and sign the declaration in Section E		
No	Please complete Sections C, D (if required), F and sign the declaration in Section E		

Section C – Statement of actual production

Provide the actual production quantity for this reporting period.*

riowide the detail production quantity for this reporting period.			
Category	Premises description	Actual production quantity (2023)	
5	Processing or beneficiation of metallic or non-metallic ore	14,366,329 tonnes	
12	Screening, etc. of material	0 tonnes	
54	Sewage facility	56 m³ per day	
61A	Solid waste facility	0 tonnes	
64	Class II or III putrescible landfill site	726 tonnes	

*Supporting information provided in the relevant conditions of the 2023 Annual Environment Report

Section D – Statement of actual Part 2 waste discharge quantity				
Provide the actual Part 2 waste discharge quantity for this reporting period.*				
Category	Premises description Actual Part 2 Waste Discharge Quantity (2023)			
5	Processing or beneficiation of metallic or non-metallic ore (tailings)	1,849,444 tonnes		
6	Mine dewatering	0.058 GL		

*Supporting information provided in the relevant conditions of the 2023 Annual Environment Report

Section E – Declaration

I declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular¹.

I consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

Position:	General Manager – Robe Valley, Iron Ore	
Date:	25.04.2024	

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.

Section F – Details of non-compliance with licence condition				
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.				
Condition number:	21	Date(s) of non-compliance:	Quarter 2 and Quar	ter 3, 2023
Details of non-complia	nce:			
Supernatant water results for thallium (TI) were not recorded at TSF4 in quarter 2 and quarter 3 in 2023 during a time when TSF4 was receiving thickened tailings.				
What was the actual (o	r suspected) er	nvironmental impact of the non-co	ompliance?	
There was no evidence of adverse environmental impact associated with the missed analyses of thallium in the TSF supernatant monitoring. In quarter 4 of the reporting period the thallium result for TSF4 supernatant was below the limit of reporting (LOR) with a result of <0.00002 mg/L.				
Cause (or suspected c	ause) of non-co	ompliance:		
Administrative error due to thallium not included in monitoring schedule following the operating license L6820 amendment received on 1 June 2023.				
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:				the
There were no adverse effects associated with the non-compliance requiring mitigation. Monitoring schedules have been reviewed to ensure all monitoring parameters as listed in condition 21 – Table 5 are sampled.				
Was this non-compliance reported to the DWER?				
Yes: Reported to D Reported to D	WER verbally WER in writing	Date: Date:		🖾 No