Annual Audit Compliance Report form

Environmental Protection Act 1986, Part V

Section A – Licence Details			
Licence Number:	L7340/1997/9	Licence File Number: DER2013/000903-2	
Licence Holder:	Pilbara Iron Company (Services) Pty Ltd		
Trading as:	Rio Tinto Iron Ore		
ACN:	107 210 248		
Registered address:	Level 22, Central Park. 152-158 St. Georges Terrace, PERTH WA 6000		
Reporting period:	1 January 2023 to 31 December 2023		

Section B – Statement of compliance with licence conditions				
Did y	Did you comply with all of your licence conditions during the reporting period?			
Yes		Please complete Sections C, D (if required) and sign the declaration in Section E		
No		Please complete Sections C , D (if required), F and sign the declaration in Section E		

Section C – Statement of actual production			
Provide the actual production quantity for this reporting period.*			
Category	Premises description	Actual production quantity (2023)	
5	Processing or beneficiation of metallic or non-metallic ore	52,952,474 tonnes	
12	Screening, etc. of material	Nil	
54	Sewage facility	211.77 cubic metres per day	
64	Class II putrescible landfill site	6,140 tonnes	
73	Bulk storage of chemicals, etc.	1,699 m³	

^{*}Supporting information provided in the relevant conditions of the 2023 Annual Environment Report

Section D – Statement of actual Part 2 waste discharge quantity			
Provide the actual Part 2 waste discharge quantity for this reporting period.*			
Category	Premises description	Actual Part 2 Waste Discharge Quantity (2023)	
5	Processing or beneficiation of metallic or non-metallic ore (tailings)	2,725,819 tonnes	
6	Mine dewatering	17.48 GL	

^{*}Supporting information provided in the relevant conditions of the 2023 Annual Environment Report

Section E – Declaration

I declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular¹.

I consent to the Annual Audit Compliance Report being published on the Department of Water and

Position:	General Manager – Yandicoogina, Iron Ore
Date:	24/04/2024

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

2023 AACR L7340 Page | 1

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.

Section F – Details of non-compliance with licence condition				
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.				
Condition number:	11	Date(s) of non-compliance:	2023 annual period	
Details of non-complia	nce:			
An assessment of site Waste Dump Landfills has identified that the JC Waste Dump Landfill contains sections where the vertical distance between the waste and the highest seasonal and expected post mining ground water level is less than 3m. The current inert waste floor level is R.L 487 to 489 and post closure GWLs are expected to be R.L 490 – 492 as per 2020 Yandicoogina closure plan (our ref: RTIO-HSE-0208486).				
What was the actual (o	r suspected) er	nvironmental impact of the non-c	ompliance?	
Nearby bores are monitored to assess groundwater chemistry in the area. No actual environmental impact has been observed during the reporting period, however the current GWLs at the site exceed the 3 m buffer requirement.				
Cause (or suspected ca	ause) of non-co	ompliance:		
Relative level variability exists within the licenced landfill area. The requirement to develop the floor of the landfill in lower lying areas as deposition has progressed to the eastern side of the facility was not realised during operation of the facility.				
Action taken to mitigat non-compliance:	Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the			
Monitoring of groundwater bores has confirmed that there have been no adverse effects as a result of the non-compliance. Landfill material will be re-handled to a compliant RL within the licenced area to accommodate a >3m buffer to post closure GWLs. Lower lying areas within the licenced area are to be developed to provide a 3m buffer. Inert waste generated at site will be deposited within the existing licenced landfill area on Roy Hill Rd adjacent to the putrescible landfill trench going forward.				
Was this non-compliance reported to the DWER?				
Yes: Reported to D'		Date:		⊠ No
☐ Reported to D'	WER in writing	Date:		

2023 AACR L7340 Page | 2

Section F – Details	of non-comp	liance with licence condition	on	
Please use a separate the reporting period.	page for each co	ondition with which the licence hol	der was non-compliar	nt at a time during
Condition number:	9	Date(s) of non-compliance:	2023 annual period	
Details of non-compli	ance:			
		otal nitrogen (780 kg/ha/year) and nits (480 kg/ha/year and 120 kg/h		18 kg/ha/year)
What was the actual (or suspected) e	nvironmental impact of the non-	-compliance?	
There was no observed	d adverse environ	mental impact associated with the	e non-compliance.	
Cause (or suspected	cause) of non-co	ompliance:		
As reported in the 2022 under normal operating		nt Mine WWTP sprayfield area is i	nsufficient to comply w	rith loading limits
Action taken to mitiga non-compliance:	ate any adverse	effects of non-compliance and p	prevent recurrence o	f the
There were no observe In the 2021 L7340 AA	CR, it was propo Mine WWTP efflu	s associated with the non-complian sed to increase the sprayfield are lent to the larger Fixed Plant WWT	ea, however, this plan	was modified to
Was this non-complia	ince reported to	the DWER?		
	•	Date:	10.000004	□ No
⊠ Reported to D\	/VER in writing	Date: 28/04/2023 our ref: RT	10-0990064	

2023 AACR L7340 Page | 3