## **Annual Audit Compliance Report form**

Environmental Protection Act 1986, Part V

Section A – Licence Details			
Licence Number:	L8688/2012/1	Licence File Number:	DER2014/000622-1
Licence Holder:	Hamersley HMS Pty Ltd		
Trading as:	Rio Tinto Iron Ore		
ACN:	115 004 129		
Registered address:	Level 18, Central Park. 152-158 St. Georges Terrace, PERTH WA 6000		
Reporting period:	1 January 2023 to 31 Dec	ember 2023	

Section B – Statement of compliance with licence conditions				
Did y	Did you comply with all of your licence conditions during the reporting period?			
Yes		Please complete <b>Sections C</b> , <b>D</b> (if required) and sign the declaration in <b>Section E</b>		
No		Please complete <b>Sections C</b> , <b>D</b> (if required), <b>F</b> and sign the declaration in <b>Section E</b>		

Section C – Statement of actual production			
Provide the actual production quantity for this reporting period.*			
Category	Premises description	Actual production quantity (2023)	
5	Processing or beneficiation of metallic or non-metallic ore	17,038,774 tonnes	
12	Screening, etc. of material	0 tonnes	
54	Sewage facility	146 m³/day	
64	Class II putrescible landfill site	622 tonnes	

<sup>\*</sup>Supporting information provided in the relevant conditions of the 2023 Annual Environment Report

Section D – Statement of actual Part 2 waste discharge quantity			
Provide the actual Part 2 waste discharge quantity for this reporting period.*			
Category	Premises description	Actual Part 2 Waste Discharge Quantity (2023)	
5	Processing or beneficiation of metallic or non-metallic ore (Tailings)	2,843,621 tonnes	
6	Mine dewatering	15.06 GL	

<sup>\*</sup>Supporting information provided in the relevant conditions of the 2023 Annual Environment Report

## **Section E – Declaration**

I declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular<sup>1</sup>.

I consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

Position:	General Manager, Greater Hope Downs – Iron Ore
Date:	24 <sup>th</sup> April 2024

2023 AACR L8688 Page | 1

<sup>&</sup>lt;sup>1</sup> It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

<sup>&</sup>lt;sup>2</sup> AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.

Section F – Details of non-compliance with licence condition						
Please use a se the reporting per		age for each con	dition with which the lic	ence holder was n	on-compliant at a tim	e during
Condition numl	oer:	10		Date(s) of non- compliance:	H2, 2023	
Details of non-c	omplia	nce:				
Standing water levels in RC14EA1026 could not be monitored in Q3 and Q4, and ground water quality could not be sampled in H2, due to the monitoring bore collapsing.						
What was the a	ctual (o	r suspected) env	vironmental impact of	the non-complian	ice?	
	There was no evidence of adverse environmental impact associated with the missed sample. Monitoring of alternative bores in close proximity to RC14EA1026 was conducted in H2, 2023.					
Cause (or susp	ected c	ause) of non-cor	mpliance:			
The monitoring bore appears to have collapsed internally and can no longer be sampled.						
Action taken to non-compliance	_	e any adverse ef	ffects of non-complia	nce and prevent re	ecurrence of the	
There were no adverse effects associated with the non-compliance requiring mitigation. A replacement bore (MB23HD40011) was drilled nearby and monitored. Bores MB12HD4007 and MB23HD40011 are in close proximity to bore RC14EA1026 and provide a good indication of the ground water levels and water quality in the area.						
During the next licence amendment, the proponent proposes to replace RC14EA1026 with MB23HD40011.						
Was this non-co	omplian	ce reported to tl	he DWER?			
_		WER verbally	Date:			⊠ No
☐ Report	ed to D	WER in writing	Date:			

2023 AACR L8688 Page | 2