

Government of Western Australia Department of Water and Environmental Regulation

# **Annual Audit Compliance Report Form**

Environmental Protection Act 1986, Part V Division 3

Once completed, please submit this form either via email to <u>info@dwer.wa.gov.au</u>, or to the below postal address:

Department of Water and Environmental Regulation Locked Bag 10 Joondalup DC WA 6919

Section A – Licence details		
Licence number:	L8848/2014/1	Licence file number:
Licence holder name:	Cleanaway Waste Management Ltd	
Trading as:	Cleanaway Waste Management Ltd	
ACN:	101 155 220	
Registered business address:	Level 4, 441 St Kilda Rd Melbourne VIC 3004	
Reporting period:	01 / 01 / 2021	to 31 / 12 / 2021

#### Section B – Statement of compliance with licence conditions

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

 $\Box$  Yes – please complete:

- section C;
- section D (if required); and
- sign the declaration in Section F.

 $\boxtimes$  No – please complete:

- section C;
- section D (if required);
- section E; and
- sign the declaration in Section F.

### Section C – Statement of actual production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed premises category	Actual production quantity	
57, 61, 61A and 62	57: 30.82 tyres 61: 2792.87 tonnes 61A: 10779.90 tonnes 62: 3343.23 tonnes	

## Section D – Statement of actual Part 2 waste discharge quantity

Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached.

Prescribed premises category		Actual Part 2 waste discharge quantity	
	Not applicable		

# Section E – Details of non-compliance with licence condition

Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.

Condition no: 1.2.8, table 1.3.3	Date(s) of non- compliance:	2018, 2019, 2020, 2021
----------------------------------	--------------------------------	------------------------

Details of non-compliance:

There are 63 24kL offshore rated ISO containers and 2 56kL tanks containing waste material that are not "Located in bunded hardstand area"

What was the actual (or suspected) environmental impact of the non-compliance?

**NOTE** – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.

No environmental impact to the environment occurred because of the non-compliance.

Fig 1: Location of tanks.



Cause (or suspected cause) of non-compliance:

Tanks not being accounted for through site inspections therefore were not acknowledged as being non-compliant.

#### Section E – Details of non-compliance with licence condition

Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:

The ISOS are currently stored on compacted ground. Each ISO is in a good condition, built to be suitable for shipping and manufactured in accordance with specifications outlined in the International Organisation for Standardisation.

Additional interim controls have been put in place at each site including:

- Daily site inspections
- ISOs have been relocated away from site boundary
- Installation of earthen bund to contain any spills if one occurs
- Additional emergency response training as required
- Spill response and adequate onsite spill equipment assessment.

Disposal pathways of the material are being investigated.

The 2 56kL tanks are planned to be removed from site.

Was this non-compliance previously reported to DWER?

 $\boxtimes$  Yes, and

Reported to DWER verbally	Date: / /
Reported to DWER in writing	Date: 15/12/2021

Section E – Details of non-compliance with licence condition			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.			
Condition no:	3.1.3	Date(s) of non- compliance:	1/03/2021, 1/03/2020, 1/03/2019
Details of non-comp	pliance:		
Not reporting in previously submitted AACRs that ISOs located on site are not being stored in accordance with the Licence requirements.			
What was the actua	al (or suspected) environmen	tal impact of the non-c	ompliance?
<b>NOTE</b> – please attack compliance took place	h maps or diagrams to provide i e.	nsight into the precise lo	cation of where the non-
No impact to the environment Cause (or suspected cause) of non-compliance:			
Tanks not being accounted for through site inspections therefore were not acknowledged as being non-compliant. This information was not communicated to DWER in the prior AACRs.			
Action taken to mitig	gate any adverse effects of n	on-compliance and pr	event recurrence of the
Licence Compliance Tool has been established to capture non-compliances with additional education provided to site staff on understanding the reporting obligations contained within a Licence.			
Was this non-compliance previously reported to DWER?			
Yes, and			
Reported to I	DWER verbally	Date: / /	
Reported to I	DWER in writing	Date: 15/12/2021	

## Section F – Declaration

I / We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular<sup>1</sup>.

I / We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

## Department of Water and Environmental Regulation

Signature <sup>2</sup> :		Signature:	
Name: (printed)		Name: (printed)	-
Position:		Position:	
Date:	25 February 2022	Date:	25 February 2022
Seal (if signing under seal):			

<sup>&</sup>lt;sup>1</sup> It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

<sup>&</sup>lt;sup>2</sup> AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.

