

Holcim (Australia) Pty Ltd 200 Adelaide Terrace EAST PERTH WA 6004 Australia ABN 87 099 732 297 Phone +61 8 92122146 Fax +61 8 92122002 www.holcim.com.au

Regional Leader, Pilbara Region Department of Water & Environmental Regulation PO Box 835 **Karratha WA 6714** 

By Email: info@dwer.wa.gov.au; hermes.medina@dwer.wa.gov.au

14 July 2020 jenny.moro@lafargeholcim.com

Dear Sir/Madam,

## RE Licence L4741/1982/12 Nickol Bay Quarry - Annual Environmental Report (AER) & Annual Audit Compliance Report (AACR) for period 1 July 2019 to 30 June 2020

Please find below and attached Holcim Australia Pty Ltd.'s (Holcim) Annual Environmental Report (AER) and Annual Audit Compliance Report (AACR). These reports are submitted to the Department of Water and Environmental Regulation (DWER) for compliance with the above-mentioned license and specifically the records required under Section 5.2.

Condition or table	Parameter
1.2.4	Immediately recover or remove and dispose of spills of
	environmentally hazardous materials outside an engineered
	containment system.

Holcim maintains a Safety, Health & Environment Management (SHE) System, in the event of a spill, control measures are implemented in accordance with the relevant spill management and communication procedures maintained by Holcim.

No spills were recorded during the reporting period.

Condition or table	Parameter		
1.2.5	Implement all practical measures to prevent stormwater run-off		
	becoming contaminated by the activities on the premises; and		
	Treat contaminated or potentially contaminated stormwater as		
	necessary prior to being discharged from the Premises		

Interceptor L1 is in place to treat water from the Holcim wash down bay which also collects some storm water runoff.

Contaminated water is either treated by this interceptor (L1) at the workshop area or is trucked offsite, so there is no discharge of treated wastewater to the environment.

Condition or table	Parameter	
2.1.1	Record of any exceedance of any descriptive or numerical limit or	
	target specified for the licence.	
Table 5.2.1	Summary of any failure or malfunction of any pollution control	
Table 5.3.1	equipment or any incidents that have occurred during the annual	
	reporting period and any action taken	

Holcim manage all incidents in a central database named INX, as part of the Holcim SHE Management System.

Number of incident/s, including measured exceedance, reported during the reporting period: 0

See attachment – INX Summary Report showing no incidents of failure/malfunction of pollution control equipment

Condition or table	Parameter	
Table 5.2.1	Measures taken to suppress dust	

Several controls have been put in place to suppress dust; these include:

- Sprinklers/Water sprays operating on the crushing plant;
- Fall height of cones kept to a minimum;
- Watercraft is used to wet down the crusher feed, the PRF; and
- Operation of a water truck when required to minimise dust from quarry roads, access ways, stockpile areas, haul roads and traffic areas.

In addition to the existing controls the contract plant also has:

• Some enclosed conveyors to assist with minimising airborne dust

Condition or table	Parameter	
Table 5.2.1	TPH as recorded in Table 3.5.1	

As there is intermittent low rainfall onsite, the Oily Water Separator (OWS) does not generate an outflow to sample. The OWS is inspected annually to check existing volumes within the tank and to determine whether it requires removal of waste by a licenced waste disposal contractor. In addition, the inflow is checked to determine whether it is blocked and requires cleaning. The OWS was recently inspected during June 2020 and the inflow was cleaned. The tank did not require removal of waste offsite by a licenced waste disposal contractor.

Condition or table	Parameter	
Table 5.2.1	Compliance as recorded in 5.1.3	

Compliance is reported via the AACR.

See Attachment – AACR

Condition or table	Parameter						
Table 5.2.1	Complaints	summary	(where	appropriate	cross	reference	with
	prevailing directions) as recorded in 5.1.4						

Holcim manage all complaints in a central database named INX, as part of the Holcim SHE Management System.

Number of complaint/s reported during the reporting period: 0

See attachment – INX Summary Report showing no complaints during the reporting period

Condition or table	Parameter	
Table 5.2.1	Monthly quantity of raw material mined (in tonnes)	

The site remained idle during the reporting period.

Month	Production (Primary Raw Feed) in Tonnes
July	0
August	0
September	0
October	0
November	0
December	0
January	0
February	0
March	0
April	0
May	0
June	0
TOTAL	0

Should you require additional information or wish to discuss further, please do not hesitate to contact me.

Yours faithfully

Jenny Moro Planning & Environment Manager



### **Annual Audit Compliance Report Form**

Environmental Protection Act 1986, Part V

Section A – Licence Details				
Licence number:	L4741/1982/12	Licence file number:	NWK1984-02	
Company name:	Holcim (Australia) Pty Ltd			
Trading as:	Holcim (Australia) Pty Ltd			
ACN:	87 099 732 297			
Registered address:	799 Pacific Highway, Chatswood, NSW 2067			
Reporting period:	01 / 07 / 2019 <b>to</b> 30 / 06 / 2020			

### Section B – Statement of Compliance with Licence Conditions

Did you comply with all your license conditions during the reporting period? (please tick the appropriate box)

 $\boxtimes \mathsf{Yes} - \mathsf{please}$  sign the declaration in Section C

 $\Box$ No – please sign the declaration in **Section C** and proceed to **Section D** 

### Section C – Statement of Actual Production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed Premises Category	Actual Production Quantity	
Category 12	0 tonnes	

# Section D – Statement of Actual Part 2 Waste Discharge QuantityProvide the actual Part 2 waste discharge quantity for this reporting period. Supporting<br/>documentation is to be attached.Prescribed Premises CategoryActual Part 2 Waste Discharge Quantity

N/A	N/A



### **Section E – Declaration**

I/We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular<sup>1</sup>. I/We consent to the Annual Audit Compliance Report being published on the Department of Environment Regulation's (DER) website.

Signature:	J.	Signature:	
Name: (printed)	John Morgan	Name: (printed)	
Position:	WA General Manager	Position:	
Seal (if signing under seal):			

AACRs can only be signed by the licensee or an authorised person with the legal authority to sign on behalf of the licensee.

<sup>&</sup>lt;sup>1</sup> It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

Section F – Details of Non-Compliance with Licence Condition									
Please use a separate page for each condition with which the licensee was non-compliant at a time during the reporting period.									
Condition no:	Ondition no:Click here to enter text.Date(s) of non- compliance:Click here to enter text.								
Details of non-com	pliance:								
Click here to e	Click here to enter text.								
What was the actua	al (or suspected) environmen	tal impact of the non-c	ompliance?						
NOTE – please attac compliance took plac	h maps or diagrams to provide i	nsight into the precise lo	cation of where the non-						
Click here to enter te									
Cause (or suspecte	ed cause) of non-compliance:								
	gate any adverse effects of r	on-compliance and pro	event recurrence of the						
non-compliance:									
Was this non-compliance previously reported to DER?									
☐ Yes, and		Deter							
Reported to DER verbally     Date:									
□ Reported to I	DER in writing	Date:							

### Event Reports

Please make y	our selection and	click search								
Company Level:				Event Category:		Event Report Type:		Event Report Subtype:		
Nickol Bay Quarry			<b></b>	Incident 🗸		Incident - Environment			~ ~	
Responsible Organisation:				Event Date From:		Event Date To:		Event Impact Type:		
			n	01-Jul-2019		30-Jun-2020		1	~	
Event Impact Seve	Event Impact Severity:			Actual Outcome:		Potential Consequence:		Status:		
~			~	×		~		~		~
Selected Level	Selected Level & Above			Selected Level & Above		Selected Level & Above		Selected Level & Above		
Search:	Search:			Search Custom Fields:		Include Closed Event Reports:				
Q Search Delete										
Date Reference	Event Type	Event Subtype	Site	Description	Actions Total / Open		Actual / Potential	Status	Close Out	
1									No records to dis	splay.
1 to 0 of 0 Events.										

### Event Reports

Please make your selection and click search											
Company Level:				Event Category:		Event Report Type:		Event Report Subtype:			
Nick	ol Bay Quarry	1			Incident 🗸		Incident - Community Complaint		~		
Respo	onsible Organi	isation:			Event Date From:		Event Date To:		Event Impact Type:		
				A	01-Jul-2019		30-Jun-2020		~		
Event Impact Severity:				Actual Outcome:		Potential Consequence:		Status:			
~				~		~	~			~	
Selected Level & Above				Selected Level & Above		Selected Level & Above		Selected Level & Above			
Search:					Search Custom Fields:		Include Closed Event Reports:				
							$\mathbf{\nabla}$				
Delete											
ų s	earch										
Date	Reference	Event Type	Event Subtype	Site	Description	Actions Total / Open		Actual / Potential	Status	Close Out	
1										No records to display.	

1 to 0 of 0 Events.

#### 🖶 Event Reports

O Ple	Please make your selection and click search										
Company Level: Nickol Bay Quarry				ф	Event Category:	~	Event Report Type: Incident - Breach of Licence	/Permit 🗸	Event Report Subtype:		~
Responsible Organisation:			٨	Event Date From: 01-Jul-2019		Event Date To: 30-Jun-2020		Event Impact Type:		~	
Event Impact Severity:			~	Actual Outcome:	~	Potential Consequence: Selected Level & Above	~	Status:		~	
Search:					Search Custom Fields:		Include Closed Event Reports:				
Q Se	Q Search Delete										
Date	Reference	Event Type	Event Subtype	Site	Description	Actions Total / Open		Actual / Potential	Status	Close Out	
1											

1 to 0 of 0 Events.