

# Government of Western Australia Department of Water and Environmental Regulation

# **Annual Audit Compliance Report Form**

Environmental Protection Act 1986, Part V Division 3

Once completed, please submit this form either via email to <a href="mailto:info@dwer.wa.gov.au">info@dwer.wa.gov.au</a>, or to the below postal address:

Department of Water and Environmental Regulation Locked Bag 10 Joondalup DC WA 6919

Section A – Licence details				
Licence number:	L6533	Licence file number:		
Licence holder name:	BGC (Australia) Pty Ltd			
Trading as:	BGC Hazelmere Industrial Complex			
ACN:	005 736 005			
Registered business address:	18 Mount Street, Perth, WA, 6000			
Reporting period:	01 / 07 /2019 <b>to</b> 30 / 06 / 2020			

### Section B - Statement of compliance with licence conditions

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

- ☐ Yes please complete:
  - section C;
  - section D (if required); and
  - sign the declaration in Section F.

#### ⋈ No – please complete:

- section C;
- section D (if required);
- section E; and
- sign the declaration in Section F.

#### Section C – Statement of actual production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed premises category	Actual production quantity
Category 35: Asphalt manufacturing Category 61A: Solid waste facility Category 77: Concrete product manufacturing	Provided separately

# Department of Water and Environmental Regulation

Provide the actual Part 2 waste disc documentation is to be attached.				
Prescribed premises category		Actual Part 2 waste discharge quantity		
			5	
Section E – Details of non-com	pliance with lice	nce conditio	n	
Please use a separate page for each at a time during the reporting period	h condition with whi	The second second second		
Condition no: 27	Date(s compli	) of non- ance:	16 July 2019	
Details of non-compliance:				
39.4 mg/L TPH recorded at the outle point reference L1.	t of the oil water sep	aration unit wl	nich discharges to emission	
What was the actual (or suspected)  NOTE – please attach maps or diagram compliance took place.  Minimal. Wash bay had minimal used to be suppressed minimal activity.	ns to provide insight in	to the precise lo	ocation of where the non-	
due to suppressed mining activity.  Cause (or suspected cause) of non-	compliance:			
Fault with oil water separator.				
Action taken to mitigate any adverse non-compliance: The wash down area was locked out of the oil water separation unit. The shad been performed one month prior shown the results have returned to matter had been resolved on 13 Aug	and subject to inves supplier pumped out r to the monitoring e previous compliant	tigation with th the sumps an vent. Subsequ	e assistance of the supplier ad cleaned the separator as ent monitoring events have	
Was this non-compliance previously	reported to DWER?			
⊠ Yes, and				
Reported to DWER verbally	Date:	1 1		
Reported to DWFR in writing	Date:	29/7/19		

# Department of Water and Environmental Regulation

# Section F - Declaration

I / We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular<sup>1</sup>.

I / We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

Signature <sup>2</sup> :		Signature:		
Name: (printed)		Name: (printed)		
Position:	General Manager HSEQ	Position:		
Date:	27 July 2020	Date:		
Seal (if signing under seal):				

 $<sup>^{1}</sup>$  It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

<sup>&</sup>lt;sup>2</sup> AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.