Annual Audit Compliance Report form

Environmental Protection Act 1986, Part V

Section A – Licence Details					
Licence Number:	L5817/1994/13	Licence File Number:	DER2014/000865		
Licence Holder:	Pilbara Iron Company (Services) Pty Ltd				
Trading as:	Rio Tinto Iron Ore				
ACN:	107 210 248				
Registered address:	L18, Central Park. 152-158 St. Georges Terrace, PERTH WA 6000				
Reporting period:	1 January 2018 to 31 December 2018				

Section B – Statement of compliance with licence conditions			
Did you co	Did you comply with all of your licence conditions during the reporting period?		
Yes 🖂	Please complete Sections C , D (if required) and sign the declaration in Section E		
No 🗌	Please complete Sections C , D (if required), F and sign the declaration in Section E		

Section C – Statement of actual production					
Provide the actual production quantity for this reporting period.*					
Category	Premises description	Actual production quantity (2018)			
54	Sewage Facility	586 cubic meters per day			

^{*}Supporting information provided in the relevant conditions of the 2018 Annual Environment Report

Section D – Statement of actual Part 2 waste discharge quantity					
Provide the actual Part 2 waste discharge quantity for this reporting period.*					
Category	Premises description	Actual Part 2 Waste Discharge Quantity (2018)			
Not Applicable – no categories relevant to Part 2 waste discharge quantity.					

^{*}Supporting information provided in the relevant conditions of the 2018 Annual Environment Report

2018 AACR L5817 Page | 1

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder

Section F – Details of non-compliance with licence condition						
	se a separate p ting period.	page for each co	ndition with which the licence hold	ler was non-compliant	at a time during	
Conditio	n number:	W2	Date(s) of non-compliance:	30 April 2018		
Details o	f non-complia	nce:				
Approxim drain.	Approximately 100m ³ of untreated wastewater overflowed from the incoming collection pit into an adjacent open drain.					
What wa	s the actual (o	or suspected) en	vironmental impact of the non-	compliance?		
There wa	There was no environmental impact from this non-compliance.					
Cause (d	or suspected c	ause) of non-co	ompliance:			
Blockage of the main inlet pipe into Settling Pond 1 due to the macerators not operating.						
	Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:					
The blockage was removed and area demarcated. A vacuum truck was engaged to remove contaminated wastewater. Granular chlorine was also spread to disinfect the area and machinery utilised to remove the surface soil from the affected area and disposed of at an approved facility.						
Was this non-compliance reported to the DWER?						
⊠ Yes:	Reported to D	·	Date: 2/05/2019		□ No	
	керопеа ю В	WER in writing	Date: 3/05/2018			

2018 AACR L5817 Page | 2