## **Annual Audit Compliance Report form**

Environmental Protection Act 1986, Part V

Section A – Licence Details			
Licence Number:	L8562/2011/1	Licence File Number:	2011/004969
Licence Holder:	Hamersley Iron Pty Limited		
Trading as:	Rio Tinto Iron Ore		
ACN:	004 558 276		
Registered address:	L18, Central Park. 152-158 St. Georges Terrace, PERTH WA 6000		
Reporting period:	1 January 2018 to 31 December 2018		

Section B – Statement of compliance with licence conditions					
Did y	Did you comply with all of your licence conditions during the reporting period?				
Yes		Please complete Sections C, D (if required) and sign the declaration in Section E			
No		Please complete <b>Sections C, D</b> (if required), <b>F</b> and sign the declaration in <b>Section E</b>			

Section C – Statement of actual production				
Provide the actual production quantity for this reporting period.*				
Category	tegory Premises description Actual production quantity (2018)			
64	Class II putrescible landfill site	0 tonnes (facility in care and maintenance)		
85	Sewage facility (1 January 2018 to 28 November 2018)	23.95 cubic metres per day		
54	Sewage facility (29 November 2018 to 31 December 2018)	29.31 cubic metres per day		

<sup>\*</sup>Supporting information provided in the relevant conditions of the 2018 Annual Environment Report

Section D – Statement of actual Part 2 waste discharge quantity					
Provide the a	Provide the actual Part 2 waste discharge quantity for this reporting period.*				
Category	Premises description	Actual Part 2 Waste Discharge Quantity (2018)			
Not Applicable – no categories relevant to Part 2 waste discharge quantity.					

<sup>\*</sup>Supporting information provided in the relevant conditions of the 2018 Annual Environment Report

Section E – Declaration			
I declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular <sup>1</sup> .  I consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.			
Signature <sup>2</sup> :			
Name: (printed)	Amit Bareja		
Position:	General Manager, Core Services (acting)– Iron ore		
Date:	30/04/2019		

<sup>&</sup>lt;sup>1</sup> It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

2018 AACR L8562 Page | 1

<sup>&</sup>lt;sup>2</sup> AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder

Section F – Details of non-compliance with licence condition				
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.				
Condition number:	2 (Version 1)	Date(s) of non-compliance:	2 June 2018	
Details of non-complia	ince:			
100 litres of untreated effluent from selector tank discharged to ground.				
What was the actual (o	or suspected) er	vironmental impact of the non-c	ompliance?	
The environment impact was low – no sensitive environmental receptors adjacent to spill location. The spill was barricaded and treated with a disinfectant.				
Cause (or suspected c	ause) of non-co	ompliance:		
The main cause of the effluent spill was a cracked pipe connection at the bottom of the anoxic selector tank.				
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:				
The effluent discharged to ground was barricaded and treated with a disinfectant. The cracked pipe was replaced with new fittings.				
Was this non-compliance reported to the DWER?				
☐ Yes: ☐ Reported to D ☐ Reported to D	WER verbally WER in writing	Date:		⊠ No

2018 AACR L8562 Page | 2

Section F – Details of non-compliance with licence condition				
Please use a separate parting period.	page for each co	ndition with which the licence holde	er was non-compliant	at a time during
Condition number:	5 (Version 1)	Date(s) of non-compliance:	29 August 2018	
Details of non-complia	nce:			
Quarterly sampling frequency (February, May and August) not adhered to.				
What was the actual (o	or suspected) er	nvironmental impact of the non-c	ompliance?	
There were no environmental impacts associated with this non-compliance.				
Cause (or suspected c	ause) of non-co	ompliance:		
Sampling collected during quarters 1, 2 and 3 did not align with licence definition of quarterly frequency. Sampling occurred in January (Q1), April (Q2) and July (Q3) rather than the February, May and August months' specified in licence.  The frequency definitions were overlooked when sampling program was communicated.				
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:				
Monitoring schedules have been updated to align with quarterly frequency definition.				
Was this non-compliance reported to the DWER?				
☐ Yes: ☐ Reported to D ☐ Reported to D	WER verbally WER in writing	Date:		⊠ No

2018 AACR L8562 Page | 3