

Government of Western Australia Department of Water and Environmental Regulation

Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V

Section A – Licence Details				
Licence number:	L8960/2016/1	Licence file number:	DER2016/000266	
Licence holder:	Water Corporation			
Trading as:	East Rockingham Wastewater Treatment Plant			
ACN:	28 033 434 917			
Registered address:	629 Newcastle Street, LEEDERVILLE, WA 6007			
Reporting period:	01/07/2022 to 30/06/2023			

Section B – Statement of 0	Compliance with I	Licence	Conditions

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

- ☐ Yes please complete:
 - section C;
 - · section D if required; and
 - · sign the declaration in Section F.
- ⋈ No please complete:
 - · section C;
 - section D if required;
 - section E; and
 - · sign the declaration at Section F.

Section C – Statement of Actual Production Provide the actual production quantity for this reporting period. Supporting documentation is to be attached. Prescribed Premises Category Actual Production Quantity 4,339 m3/d (details in Annual Environmental Report)

for this reporting period. Supporting	
Actual Part 2 Waste Discharge Quantity	

Section E - Deta	ails of Non-Complian	ce with Licence Condi	ition
Please use a sepa at a time during the		ition with which the licence	e holder was non-compliant
Condition no:	1.2.4	Date(s) of non- compliance:	17/12/2021; 01/06/2022
Details of non-com	pliance:		
being stored in a s	ealed bin, on a hard star	nents of condition 1.2.4 in nd area which returns sluc and area is not bunded.	relation to grits and screens lge leachate to the start of
What was the actu	al (or suspected) enviro	nmental impact of the non	-compliance?
NOTE – please attac		ovide insight into the precise	location of where the non-
leachate to the to t area does not pose	he start of the treatment	pills or overflows to the en	ding at the entrance to this nvironment; therefore there is
Cause (or suspect	ed cause) of non-compli	ance:	
contained in the bit which drains to the immediately downs	ns, however should any return liquor pump stati stream of the inlet works	on. From here leachate is at the head of the plant. I	eachate is primarily the area drains to a sump, returned to the bioselector, t was determined at design ks, therefore bunding was
Action taken to mit non-compliance:	igate any adverse effect	s of non-compliance and p	prevent recurrence of the
An amendment of	the Licence is required t requested as part of the		enings are being managed
Was this non-comp	oliance previously report	ed to DWER? Yes	
x□ Yes, and			
☐ Reported to	DWER verbally	Date: / /	
x☐ Reported to	Reported to DWER in writing Date: 01 / 10 / 22 (AACR)		

Section F - Declaration

I / We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular¹.

I / We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

Signature ² :		Signature:	
Name: (printed)		Name: (printed)	
Position:	General Manager Operations	Position:	
Date:	13 SEPT 2023	Date:	
Seal (if signing under seal):			

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.