



ABN: 50 860 676 021

Enquiries: Ms Jessica Sheppard (08) 9323 4614  
Our Ref: 08/104  
Your Ref: CPS817/3

26 June 2012

Mr Matt Warnock  
Department of Environment and Conservation  
Locked Bag 104  
Bentley Delivery Centre  
BENTLEY WA 6983

Dear Matt,

**CLEARING PERMIT CPS 817 REPORTING OF ACTIVITIES FOR 2012**

Main Roads WA is pleased to provide documentation in accordance with Condition 17 of state-wide clearing Permit CPS 817/3.

Electronic copies of relevant environmental impact assessment reports, management plans, revegetation plans and offset proposals, including ESRI Shapefiles as required, are provided on the enclosed CD.

Main Roads cleared native vegetation under CPS817 for one project within the period 1<sup>st</sup> January to 31<sup>st</sup> December 2012. This project followed two extreme storm events on 10<sup>th</sup> and 12<sup>th</sup> of June across the South West of WA. Main Roads South West Region was required to undertake an extensive clean-up program to restore the road network to a safe condition. The focus of the clean-up was to clear the roads and remove hazards which could cause risks to road users.

Please find additional information on the project works in the attachment document.

I trust that this satisfies the reporting requirements of state-wide clearing Permit CPS 817. If you require any further information please contact my Principal Environment Officer Ms Jessica Sheppard on 9323 4614.

Yours sincerely



Murray Limb  
MANAGER ENVIRONMENT

## CPS817/3 Reporting for 2012 Additional information

**Project Activities Description:** Crews were mobilised to initially clear the roads leaving piles of vegetation along the roadside. The final clean-up involved the removal of these piles as well as accumulated debris and hazardous trees from the road reserve areas. Particular attention was given to the removal of fallen trees on fence lines to allow their repair so as to prevent the movement of stock onto the road.

Due to the enormous scale of the works and for safety reasons, machinery was used wherever possible, except in identified significant environmental areas; where hand tools and man-handling techniques were employed. Clean-up crews exercised judgement in clearing any dead / dangerous trees on a case by case basis. MRWA is unable to advise the exact hectares cleared because of the nature of the clean-up and the various exemptions and approval used to complete the project. A list of all the roads where project activity occurred is listed below.

Road Number	Road Name
H02	MELVILLE MANDURAH HWY
H09	SOUTH WESTERN HWY
H15	KWINANA FWY
H43	BUSSELL HWY
H45	COALFIELDS HWY
H57	FORREST HWY
H61	AUSTRALIND ROELANDS LINK
M03	BANNISTER MARRADONG
M06	BRIDGETOWN BOYUP BROOK
M08	VASSE
M13	DONNYBROOK KOJONUP
M23	PINJARRA
M24	MUIR
M27	BROCKMAN
M36	PEMBERTON NORTHCLIFFE
M37	COLLIE LAKE KING
M42	GOODWOOD
M43	CAVES
M46	COLLIE MUMBALLUP
M52	BOYANUP PICTON
M53	PINJARRA WILLIAMS
M61	BOYANUP CAPEL
M73	GREENLANDS RD
M74	LAKELANDS LAKE CLIFTON
M81	SUES RD